



## Results of inspection of Reactor No. 5 condensate tank



Condensate Tank Floor Image Diagram (side view)

